



LOGIN

Please enter your details below to access TOPIx.

Username

Password

Login

Register

Forgotten password?

1. Indtast brugernavn og kodeord her og klik på Login.



TOPIx Enhancements

Retailer Vehicle Park and Technician Repair Workflow
[View](#)

Skal Google Chrome gemme din adgangskode for dette website?

Brugernavn info@dbr.dk

Adgangskode

[Gem](#) [Aldrig](#)

VIN SELECTION

Please enter your 17 character Vehicle Identification Number

OR

Enter the last 8 characters

-- Recent --

Find

[Search via Model Selection](#)

ACTIVITY STREAM

- ▲ N158v2 - Fuel Fired Booster Heater Inhibited
- ▲ N056v2 - Child Seat Handbook Table - Third Row Seats
- ▲ H083v2 - Fuel Fired Booster Heater (FFBH) Remote Control Not Paired To The Vehicle
- ▲ N155 UPS0418-5 - Incontrol Touch Pro Touchscreens Flickering
- ▲ N165 - Tire Pressure Monitoring System (TPMS) Incorrect for 20 Inch Tires in Instrument Cluster (IC)
- ▲ N151v2 - Automatic Temperature Control Module Software Update
- ▲ N135v2 - Air Suspension And Adaptive Damping (AD) Warning Message
- ▲ K417v2 - Cross Brace Creak
- ▲ Q627v6 - No 'Engine Service' Message Displayed In The Message Center

Indtast bilens stelnummer her.
Klik derefter på Find





TOPIX

Currently Viewing
XE / X760 2016
SAJAB4DN6GA912326
> Vehicle home page

Vehicle Summary > View all vehicle details



OPTION SELECTION

To proceed, please select which activity you are going to perform from the list below.

Maintenance, PDI & OSH

The vehicle requires a service or a pre-delivery inspection.

Accessory and Configuration

The vehicle requires an accessory or configurable option.


Fault and Breakdown

There is a concern on the vehicle that needs rectification.

Browse all

Just take a look around.

Tryk her



OUTSTANDING CAMPAIGNS

⚠ 105A -



Currently Viewing
XE / X760 2016
SAJAB4DN6GA912326
> Vehicle home page

Vehicle Summary > View all vehicle details



1. Klik på OSH

- Vehicle
- Search
- Documents
- OSH
- RTS

VEHICLE FEATURES

WVTA	e11*2007*46*2150
Body style	4 DOOR CONVERSION FEATURE
Version	2.0L I4 AJ200 DSL MID SER CONV
Drive	LHD
Transmission	6-Speed Manual 2WD
Engine	2.0L Diesel
Trim	VENEER-GLOSS BLACK
Colour	POLARIS WHITE/FUJI WHITE

OUTSTANDING CAMPAIGNS

- ⚠ I189 - XE JAGUAR CARE BRAKE FLUID (YEAR 2)
- ⚠ I192 - XE JAGUAR CARE 2ND SERVICE
- ⚠ I193 - XE JAGUAR CARE 3RD SERVICE
- ⚠ I194 - XE JAGUAR CARE 4TH SERVICE
- ⚠ I195 - XE JAGUAR CARE 5TH SERVICE
- ⚠ I197 - XE JAGUAR CARE 1ST SERVICE

ACTIVITY STREAM

- ⚠ N158v2 - Fuel Fired Booster Heater Inhibited
- ⚠ N056v2 - Child Seat Handbook Table - Third Row Seats
- ⚠ H083v2 - Fuel Fired Booster Heater (FFBH) Remote Control Not Paired To The Vehicle
- ⚠ N155 UPS0418-5 - Incontrol Touch Pro Touchscreens Flickering
- ⚠ N165 - Tire Pressure Monitoring System (TPMS) Incorrect for 20 Inch Tires in Instrument Cluster (IC)
- ⚠ N151v2 - Automatic Temperature Control Module Software Update
- ⚠ N135v2 - Air Suspension And Adaptive Damping (AD) Warning Message
- ⚠ K417v2 - Cross Brace Creak
- ⚠ Q627v6 - No 'Engine Service' Message Displayed In The Message Center

PREVIOUS SERVICE RECORDED:

Job Date: 19/08/2015
Odometer: 30 km
Type: Pre-Delivery Inspection

CURRENT RECORD

Vehicle
XE / X760, 2.0L Diesel, 4 DOOR CONVERSION FEATURE, 6-Speed Manual 2WD

VIN
SAJAB4DN6GA912326

Registration Plate No
AX12951

Warranty Start Date
30-Jul-2015

Registrer udført service i
nedenstående felter

ADD NEW RECORD

Service Completed *

-- Please select --

Job Number *

Job Date *

22/02/2018

Odometer Reading *

Miles km

Vehicle's actual distance travelled

Select other Service Items and related Jobs Completed:

- Renewal of Oil and Oil Filter
- Renewal of Brake Fluid
- Renewal of Pollen Filter
- Renewal of Engine Air Filter
- Renewal of Fuel Filter
- Renewal of Transmission Fluid
- Renewal of Engine Coolant
- Renewal of Spark Plugs
- Renewal of Cam Belt
- Renewal of Transfer Case Fluid
- Renewal of Flexible Brake Hoses
- Renewal of Alarm Handset Batteries
- Renewal of Air Bag
- Renewal of Bearing Grease
- Renewal of Air Suspension Inlet Filter
- Renewal of Dynamic Response Filter
- Renewal of Supercharger Drive Belt
- Renewal of Front Differential Fluid
- Renewal of Rear Differential Fluid
- Renewal of Ancillary Drive Belt
- Renewal of Climate Controlled Seat Filters
- New Odometer Installed
- Air Conditioning Service
- 'Pre Winter' Check
- 'Pre Summer' Check

Next Scheduled Service Due:

Service Type:

By Odometer Reading:

or By Date:

Current Annual Mileage Calculation:

Date Due using Annual Mileage:

Date for næste VHC (Vehicle Health Check)

Submit Cancel



Currently Viewing
 XE / X760 2016
 SAJAB4DN6GA912326
 > Vehicle home page

Vehicle Summary > View all vehicle details



VEHICLE SEARCH DOCUMENTS **OSH** RTS

SERVICE DUE

Last Service Recorded:
 Type: Pre-Delivery Inspection at 30 km
 Date: 19-Aug-2015

Next Scheduled Service Due:
 Type: 34.000 km / 24 months
 By Odometer reading 34.030 km or: By Date: 19-Aug-2017
 -187 days
 Until your next service is due

VEHICLE DETAILS

VIN
 SAJAB4DN6GA912326
Registration Plate No
 AX12951
Model
 XE / X760
Model Year
 2016
Colour
 POLARIS WHITE/FUJI WHITE

SERVICE HISTORY

Showing 1 - 1 of 1 Service Records

Order by Descending

#	Dealer Name	Dealer Type	Code	Dealer city	Service date	Service type	Odometer	Actions
1	Terminalen Arhus		JO21702737	Risskov	19/08/2015	Pre-Delivery Inspection	30 km	+ -



Online Service Historik Kundens kopi.

Støttenummer: SALVA28C4FH088181 Repareringsnummer: AV676/1 Garanti start (dato): 26/06/2015
 Model: Range Rover Evoque / L538 Repareringsland: Danmark
 Motor: 2.2L Diesel
 Farve: COIRIS GREY
 Serviceintervaller: Hver 20.000 kilometer eller 12 måneder (hvad der måtte komme først)
 Næste besøg: 78.000 km / 30 måneder Forfaldsdate: 14/12/2016 (baseret på nuværende gennemsnitlige brugsnærsed (97.127 kilometer) eller ved kilometertal: 78.000 kilometer (hvad der måtte komme først) (Se venligst din garanti og KVL i vejledning for detaljer vedr. intervallerne og eftersynenes indhold.)
 08/09/2017 - hvis almindeligt kørselsforbrug

Seneste optagelse				
Reparatur	Ordrenummer	Udført (dato)	Kilometerlæser	Detaljer
Cor-Center Røndervej 8 Hjulsbo F 4800 Danmark 88670933	11111	09/09/2016	52.000 kilometer	Planmæssigt service udført. 57.000 kilometer/24 måneder Beståede service punkter Udsugning af olie og oliefilter Udsugning af pollen filter
Tidligere optagelse				
Reparatur	Ordrenummer	Udført (dato)	Kilometerlæser	Detaljer
Or eller A/S Åmbovej 7 Vinding 1000 Danmark	323712	31/05/2016	25.408 kilometer	Planmæssigt service udført. 26.000 kilometer/12 måneder Beståede service punkter Udsugning af olie og oliefilter Udsugning af pollen filter Udsugning af luftfilter
Terminaten Århus A/S Grendvej 337 Horslev 8240 Danmark	674443	23/06/2015	9 kilometer	Planmæssigt service udført. Søjsklarbering Beståede service punkter Ise relevant